

31735 5 LTS Chandelier Assembling Instruction

1. Unpack the carton and place the fixture on a flat surface. Attention: All necessary hardware and loose components have been verified for this fixture and are packed inside. Do not discard inner packing until you have inspected it thoroughly.
2. Thread the NIPPLE (C) into the TOP COUPLING (M). Secured by the HEXNUT (B).
3. Place the METAL CAP (D), MOSAIC COVER (E), COVER (F), TOP MOSAIC COLUMN (G) through the NIPPLE (C) onto the BODY (R). Tighten with the hex nut (B).
4. Thread the LOOP (A) onto the NIPPLE (C). Hang tightens until snug.
5. Measure the height from hanging fixture to your ceiling. Cut the excess chain and wire to fit the height. Put the fixture onto the chain.
6. Place the CLEAR GLASS (K), CAP (I), OPAL GLASS (J), through the socket onto the BOBECHE (L). Thread the SOCKET RING (H) onto the socket. Adjust the OPAL GLASS (J), CLEAR GLASS (K) by hand until level then secure the glass by the SOCKET RING (H).
7. Thread the NIPPLE (N) onto the BOTTOM COUPLING (Q) secured by the HEX NUT (B).
8. Place the BOTTOM MOSAIC COLUMN (O) COVER (R) through the NIPPLE (N). Tighten with the FINIAL (P).
9. Follow the wattage label on the SOCKET RING (H) and install proper bulbs (not provided) onto the sockets.

